




X125 350 BAR SUBMERSIBLE STAND-ALONE LINEAR **POSITION SENSOR**

INTRINSICALLY SAFE FOR HAZARDOUS GAS/VAPOUR ATMOSPHERES

- **Intrinsically safe for Gas to:** Ex II 1G
- Travel set to customer's requirement
- **Compact and self-contained**
- High durability and reliability
- High accuracy and stability
- Sealing to IP68 350 Bar



where hazardous surface conditions may exist. It remains an affordable, durable, high-accuracy position. The unit is highly compact and spaceefficient, being responsive along almost its entire length. Like all Positek® sensors, the X125 provides a linear output proportional to displacement. Each sensor is supplied with the output calibrated to the travel required by the customer, from 5 to 800mm and with full EMC protection built in. The sensor is very robust, the body and push rod being made of stainless steel for long service life and environmental resistance. Overall performance, repeatability and stability are outstanding over a wide temperature range. The sensor is easy to install with mounting options including M8 rod eye bearings and body clamps. The push rod can be supplied free or captive with male M8 thread, an M8 rod eye, dome end or magnetic tip. M12 and 1/2" rod eye option available. Captive push rods can be sprung

loaded, in either direction, on sensors up to 300 mm of travel. The X125 also offers a range of mechanical options, environmental sealing is to



SPECIFICATION

Dimensions

Body diameter Body length (Axial version) Body length (Radial version) 40 mm electronics and 35 mm measurement length + 184 mm measurement length + 189 mm

measurement length + 7 mm, OD 12.6 mm Push rod extension Push rod extension
For full mechanical details see drawing X125-11

ndependent Linearity

\$\leq \pmu 0.25\% \text{ FSO } \@ 20\circ - \text{ up to } 450 \text{ mm}

\$\leq \pmu 0.5\% \text{ FSO } \@ 20\circ - \text{ over } 450 \text{ mm}

emperature Coefficients

\$\leq \pmu 0.5\% \text{ FSO } \@ 20\circ \text{ over } 450 \text{ mm}

\$\leq \pmu 0.5\% \text{ FSO } \@ 20\circ \text{ over } 450 \text{ mm}

\$\leq \pmu 0.5\% \text{ FSO } \@ 20\circ \text{ over } 450 \text{ mm}

\$\leq \pm 0.5\% \text{ FSO } \@ 20\circ \text{ over } 450 \text{ mm}

\$\leq \pm 0.5\% \text{ FSO } \@ 20\circ \text{ over } 450 \text{ mm}

\$\leq \pm 0.5\% \text{ FSO } \@ 20\circ \text{ over } 450 \text{ mm}

\$\leq \pm 0.5\% \text{ FSO } \@ 20\circ \text{ over } 450 \text{ mm}

\$\leq \pm 0.5\% \text{ FSO } \@ 20\circ \text{ over } 450 \text{ mm}

\$\leq \pm 0.5\% \text{ FSO } \@ 20\circ \text{ over } 450 \text{ mm}

\$\leq \pm 0.5\% \text{ FSO } \@ 20\circ \text{ over } 450 \text{ mm}

\$\leq \pm 0.5\% \text{ FSO } \@ 20\circ \text{ over } 450 \text{ mm}

\$\leq \pm 0.5\% \text{ FSO } \@ 20\circ \text{ over } 450 \text{ mm}

\$\leq \pm 0.5\% \text{ FSO } \@ 20\circ \text{ over } 450 \text{ mm}

\$\leq \pm 0.5\% \text{ over } \text{ over }

Independent Linearity

Temperature Coefficients < ± 0.01%FS/°C Offset **Frequency Response** > 10 kHz (-3dB)

Infinite < 0.02% FSO Resolution Noise Intrinsic Safety Fx II 1G

Ex ia IIC T4 Ga (Ta= -40°C to 80°C)

Approval only applies to the specified ambient temperature range and atmospheric conditions in the range 0.80 to 1.10 Bar, oxygen $\le 21\%$

(with cable)

Environmental Temperature Limits (Non Icing)

-4 to +50°C Operating Storage -4 to +50°C Sealing EMC Performance IP68 350 Bar

EN 61000-6-2, EN 61000-6-3 IEC 68-2-6: 10 g IEC 68-2-29: 40 g Vibration Shock

MTBF 350,000 hrs 40°C Gf **Drawing List**

Sensor Outline 3D models, step or .igs format, available on request.

Do you need a position sensor made to order to suit a particular installation requirement or specification? We'll be happy to modify any of our designs to suit your needs please contact us with your requirements.



IP68 350 Bar.



X125 350 BAR SUBMERSIBLE STAND-ALONE LINEAR POSITION SENSOR

INTRINSICALLY SAFE FOR HAZARDOUS GAS/VAPOUR ATMOSPHERES

Intrinsically safe equipment is defined as "equipment which is incapable of releasing sufficient electrical or thermal energy under normal or abnormal conditions to cause ignition of a specific hazardous atmosphere mixture in its most easily ignited concentration." ATEX / IECEx / UKEX approved to;

Ex II 1G

Ex ia IIC T4 Ga (Ta= -40°C to 80°C)

Designates the sensor as belonging to; Group II: suitable for all areas **except mining**, Category 1 G: can be used in areas with continuous, long or frequent periods of exposure to hazardous gas / vapour (Zones 2 to 0).

Gas / Vapour:

Protection class ia, denotes intrinsically safe for all zones

Apparatus group IIC: suitable for IIA, IIB and IIC explosive gas / vapour.

Temperature class T4: maximum sensor surface temperature under fault conditions 135°C.

Ambient temperature range extended to -40°C to +80°C.

It is imperative Positek[®] intrinsically safe sensors be used in conjunction with a galvanic barrier to meet the requirements of the product certification. The Positek X005 Galvanic Isolation Amplifier is purpose made for Positek IS sensors making it the perfect choice. Refer to the X005 datasheet for product specification and output configuration options.


For cable lengths exceeding 10 metres a five wire connection is recommended to eliminate errors introduced by cable resistance and associated temperature coefficients.

ATEX / IECEx / UKEX approved sensors suitable for dust (E series) and mining (M series) applications, are also available from Positek.

| X125 | а | b | С | d | е | f | g | h | j |
|------|--------------|---|-------------|--------|--------|--------|--------|--------|------|
| | Displacement | Α | Connections | Option | Option | Option | Option | Option | Z000 |

| a Displacement | | Value | | | |
|---|--------------------------------------|-------|--|--|--|
| Factory set to any length 254 mm) | n from 0-5 mm to 0-800 mm (e.g. 0- | 254 | | | |
| b Output | | | | | |
| Supply V _{dc} (tolerance) | Output | Code | | | |
| +5V (4.5 - 5.5V) | 0.5 - 4.5V (ratiometric with supply) | A | | | |
| Supply Current 10mA typical, 12mA max. | | | | | |
| c Connections | | Code | | | |
| Connector axial IP68 350 | J50 | | | | |
| Connector radial IP68 35 | K50 | | | | |
| Supplied with an over-moulded MC IL-4-F connector with 0.5 m, 4-core 20 AWG (0.5mm²) EPDM cable assembly, and locking collar as standard. | | | | | |
| d Body Fittings | | Code | | | |
| None default | blank | | | | |
| M8 Rod-eye bearing radia | N | | | | |
| e Body Clamps | | Code | | | |
| Body Clamps 1 pair | P | | | | |
| Body Clamps 2 pairs | | P2 | | | |

| f Sprung Push Rod | | | | |
|---|---|-------|--|--|
| Not sprung default | | blank | | |
| Spring extend | 300 mm maximum displacement and captive | R | | |
| Spring retract | push rod only. | S | | |
| g Push Rod Fittings | | | | |
| Male thread M8x1.25x10 long default | | | | |
| Dome end with spring extend option 'R' | | | | |
| M8 Rod-eye Bearing | | | | |
| Magnetic Tip | | | | |
| h Push Rod | | | | |
| Captive push rod retained default | | | | |
| Non-captive push rod can depart body | | | | |
| j Z-code | | | | |
| Calibration to suit X005 required | | | | |
| Tighter Independent Linearity; ≤± xx% FSO @20°C ≤± 0.1% 0 - 10 mm min. to 0 - 450 mm ≤± 0.25% 0 - 451 mm to 0 - 600 mm ≤± 0.5% 0 - 601 mm to 0 - 800 mm max. | | | | |
| 1/2" Rod eyes with options 'N' and/or 'U' | | | | |
| M12 Rod eyes with options 'N' and/or 'U' | | | | |





For further information please contact: www.positek.com sales@positek.com



Three or Five-Wire Mode Connection FOR INTRINSICALLY SAFE SENSORS IN HAZARDOUS ATMOSPHERES

The aim of this document is to help readers who do not understand what is meant by three or five wire modes of connection between the galvanic isolation amplifier and sensor, and the factors behind them. It is by no means an in-depth technical analysis of the subject.

Whether opting for a pre-wired Positek® Intrinsically Safe sensor or one with a connector, choosing the right mode of connection and cable to suit the application requires careful consideration.

Interconnecting cables are not perfect conductors and offer resistance to current flow, the magnitude of resistance[†] depends on conductors resistivity, which changes with temperature, cross sectional area[‡] and length. If the voltage were to be measured at both ends of a length of wire it would be found they are different, this is known as volts drop. Volts drop changes with current flow and can be calculated using Ohm's law, it should be noted that volts drop occurs in both positive and negative conductors. The effects of volts drop can be reduced by increasing the conductors cross sectional area, this does not however eliminate the effects due to temperature variation. There are instances where large cross-section cables are not practical; for example most standard industrial connectors of the type used for sensors have a maximum conductor capacity of 0.75mm², copper prices and ease of installation are other considerations.


This is important because the effects of volts drop can significantly alter the perceived accuracy of the sensor which is ratiometric i.e. the output signal is directly affected by the voltage across the sensor. Changes in temperature will also be seen as gain variation in the sensor output.

Three wire mode connections are common and are suitable in most cases with short or moderate cable runs. Applications that do not require a high degree of accuracy but have cable runs, say in excess of 10m, volts drop can reduced by introducing a terminal box close to the sensor and using a larger cross-section cable for a majority of the cable run. Sensors supplied with three core cable are calibrated with the cable fitted which largely eliminates errors due to conductor resistance at room temperature however, as mentioned above, small gain errors due to temperature fluctuations should be expected.

Five wire mode connections have significant benefits as losses in the positive and negative conductors are compensated for by the galvanic isolation amplifier which can 'sense' the voltage across the sensor and dynamically adjust the output voltage so that the voltage across the sensor is correct. The effects of cable resistance and associated temperature coefficients are eliminated allowing for smaller conductors than a three wire connection for the same cable run. The amplifier can compensate for up to 15Ω per conductor with a current flow of 15mA, which is more than adequate for 150m of 0.25mm^2 cable, longer lengths will require larger conductors.

For this reason Positek® recommends five wire connections for cable lengths exceeding 10 metres in 0.25 mm² cable to preserve the full accuracy of the sensor.

See illustrations below for examples of connecting a sensor to the galvanic isolation amplifier.



The table above shows recommended conductor sizes with respect to cable length for both three and five wire connections, based on copper conductors. Three wire connections will introduce a gain reduction of 5% and a $\pm 1\%$ temperature dependence of gain over the range -40°C to +80°C for the cable temperature. (i.e. about -150 ppm/°C for the maximum lengths shown and less pro rata for shorter lengths.)

It should be noted that the maximum cable length, as specified in the sensor certification, takes **precedence** and **must not** be exceeded.

Positek® sensors are supplied with three core 0.25 mm² cable as standard, however five core 0.25 mm² cable can be supplied on request. The galvanic isolation amplifier is available as;

G005-*** for 'G' and 'H' prefix sensors X005-*** for 'E', 'M' and 'X' prefix sensors



For further information please contact:

www.positek.com sales@positek.com

Tel: +44(0)1242 820027 fax: +44(0)1242 820615

Positek, Andoversford Industrial Estate, Cheltenham GL54 4LB. U.K.


 $^{^{\}dagger}$ R = ρ L/A ρ is the resistivity of the conductor (Ω m) L is the length of conductor (m) A is the conductor cross-sectional area (m^2).

^{*}It is presumed that **d**irect **c**urrent flow is uniform across the cross-section of the wire, the galvanic isolation amplifier and sensor are a dc system.




Installation Information

X125 350BAR SUBMERSIBLE STAND-ALONE LINEAR POSITION SENSOR INTRINSICALLY SAFE FOR HAZARDOUS GAS/VAPOUR ATMOSPHERES



Connector Pin Layout: MC BH 4 M (face view) ∕4⊚ **01**



Putting Into Service: The sensor must be used with a galvanic isolation barrier designed to supply the sensor with a nominal 5V and to transmit the sensor output to a safe area. The barrier parameters must not exceed:

Ii = 0.20AUi = 11.4V $Ci = 1.36 \mu F^*$ $Li = 860 \mu H^*$ (with maximum cable length) $Ci = 1.16 \mu F$ $Li = 50\mu H$ (without cable)

The sensor is certified to be used with up to 1000m of cable, cable characteristics must not exceed:-

≤ 200 pF/m 200 nF Capacitance: or max. total of: Inductance: ≤ 810 nH/m or max. total of: 810 µH

Approval only applies to specified ambient temperature range and atmospheric conditions in the range: 0.80 to 1.10 Bar, oxygen ≤ 21%.

The performance of the sensor may be affected by voltage drops associated with long cable lengths; for cable runs exceeding 10 metres a five wire connection is recommended to eliminate errors introduced by cable resistance and associated temperature coefficients.

N.b. Cable free end must be appropriately terminated, including preventing water ingress into the cable. See page 2 for connector handling instructions.

Special Condition for Safe Use:

The apparatus does not meet the 500 V r.m.s dielectric strength test between circuit and frame, in accordance with clause 6.3.13 of IEC 60079-11:2011. This must be taken into consideration on installation.

Under certain extreme circumstances, the non-metallic and isolated metal parts incorporated in the enclosure of this equipment may generate an ignition-capable level of electrostatic charge. Therefore the equipment shall not be installed in a location where the external conditions are conducive to the build-up of electrostatic charge on such surfaces. This is particularly important if the equipment is installed in a zone 0 location. In addition, the equipment shall only be cleaned with a damp cloth.


Use: The sensor is designed to measure Rotary displacement and provide an analogue output signal.

Assembly and Dismantling: The unit is not to be serviced or dismantled and re-assembled by the user.

Maintenance: No maintenance is required.

Mechanical Mounting: Depending on options; Body can be mounted by rod eye bearing or by clamping the sensor body - body clamps are available, if not already ordered. Target by M8x1.25 male thread, rod eye bearing or magnetic tip. It is assumed that the sensor and target mounting points share a common earth.

Output Characteristic: Target is extended 7 mm from end of body at start of normal travel. The output increases as the target extends from the sensor body, the calibrated stroke is between 5 mm and 800 mm.



Incorrect Connection Protection levels:- The sensor is not protected against either reverse polarity or over-voltage. The risk of damage should be minimal where the supply current is limited to less than 50mA.



^{*}Figures for 1km cable where: Ci = 200pF/m & Li = 810nH/m




Installation Information X125 350BAR SUBMERSIBLE STAND-ALONE LINEAR POSITION SENSOR INTRINSICALLY SAFE FOR HAZARDOUS GAS/VAPOUR ATMOSPHERES

Connector Mating Instructions Handling

- Always apply grease mating
- · Disconnect by pulling straight, not at an angle
- Do not pull on the cable and avoid sharp bends at cable entry
- When using bulkhead connector, ensure that there are no angular load
- Do not over-tighten the bulkhead nuts
- Connectors should not be exposed to extended periods of heat or direct sunlight. If a connector becomes very dry, it should be soaked in fresh water before use

Greasing and mating above water (dry mate)







- Connectors must be greased with Molykote 44 Medium before every mating
- A layer of grease corresponding to approximately 1/10 of the socket depth should be applied to the female connector
- The inner edge of all the sockets should be completely covered, and a transparent layer of grease left visible on the face of the connector
- After greasing, fully mate the male and female connector in order to secure optimal distribution of grease on pins and in sockets
- To confirm that the grease has been sufficiently applied, demate and check for grease on every male min. Then re-mate the connector

Cleaning

- General cleaning to remove any accumulated sand or mud on a connector should be performed using spray based contact cleaner (isopropyl alcohol)
- New grease must be applied again prior to mating

Greasing and mating under water (wet mate)





- Connectors must be greased with Molykote 44 Medium before every mating
- A layer of grease corresponding to approximately 1/3 of the socket depth should be applied to the female connector
- All sockets should be completely sealed, and a transparent layer of grease left visible on the face of the connector
- After greasing, fully mate the male and female connector and remove any excess grease from the connector joint

